


# Excess Inventory

To order contact Kim @ 715-360-8002 or Rolf @ 715-360-3660

(Rev. 06-27-2018)

Description	New	Used	Illustration	Your Cost
<b><i>Air Compressors</i></b>				
<p><b>Compressor # 1</b>  <b>7.5 Hp Ingersoll Rand</b>  <b>Model # 2475 T-30</b>  <b>Serial # 02017213</b>  <b>Electronic Drain</b>  <b>No Motor, but can be provided.</b>  <b>PM - new Intake Filter</b>  <b>Changed Oil in Compressor</b>  <b>New Pressure Switch</b>  <b>New Check Valve in Tank</b></p>		<b>X</b>		<p><b>\$875</b> <b>OBO</b></p>
<p><b>Compressor # 2</b>  <b>7.5 Hp Ingersoll Rand</b>  <b>Model 2475</b>  <b>Serial # 1119683</b>  <b>with air-cooled After Cooler</b>  <b>Motor - Ing.Rand / WEQ</b>  <b>Single Phase, 3520 RPM</b>  <b>208/230 V 34 - 32 Amps</b>  <b>Cont. Duty 60 Hz SF 1.15</b>  <b>Electronic Drain</b>  <b>PM - new intake Filter</b>  <b>Changed Oil in Compressor</b></p>		<b>X</b>		<p><b>\$950</b> <b>OBO</b></p>
<p><b>Compressor # 3</b>  <b>Dual Unit; Brand SpeedAir</b>  <b>w/7.5 Hp Motors</b>  <b>Baldor/Reliant TEFC</b>  <b>1770 RPM 60 Hz 3ph.</b>  <b>Compr. Model # IWD63</b>  <b>Serial # D053000 &amp; D02225</b>  <b>23.5 CFM @ 175 psi/unit</b>  <b>Twin Tower Drier;</b>  <b>Pre- &amp; Coalescing Filter;</b>  <b>Electronic Drain.</b>  <b>PM Service:</b>  <b>(1) New aftercooler</b>  <b>(1) New Pressure Switch</b>  <b>Changed compressor oil</b></p>		<b>X</b>		<p><b>\$3,500</b> <b>OBO</b></p>

**Compressor # 4**  
**20 Hp Quincy Screw Comp.**  
**Model QNW**  
**Serial # 963 30**  
**Lincoln Electric ODP Motor**  
**1750 RPM**  
**208/230/460 Volt**  
**54.5 / 49.6 / 24.8 Amps**  
**26045 Hrs**  
**PM: New pressure gauge,**  
**Oil Change,**

X



**\$3,750**  
**OBO**

**Compressor # 5**  
**5 Hp Kaeser Screw Compr.**  
**Model SX-6**  
**480 V 60 Hz 3 Ph**  
**3600 RPM**  
**21 CFM @ 110 psi**  
**Year 2006**  
**16,000 hrs**  
**Tested - Runs like a charm!**

X



**\$2,750**  
**OBO**