


Excess Inventory


To order contact Kim @ 715-360-8002 or Rolf @ 715-360-3660

(Rev 06-30-18)

Description	Illustration	Your Cost
<i>Ball Check & ButterFly Valves</i>		
1 1/2" AlfaLaval/TriClover with AirBlow		\$ 510
1 1/2" AlfaLaval/TriClover without AirBlow		\$ 385
2" AlfaLaval/TriClover with AirBlow		<p style="color: red;">Waiting for 2 1/2" HD Clamps</p> \$395+\$175
2" AlfaLaval/TriClover without AirBlow		\$ 395
1 1/2" Stainless Products with AirBlow		\$ 265

<p>1 1/2" Stainless Products without AirBlow</p>			<p>\$ 180</p>
<p>1 1/2" straight-thru Ball Valve Type 1 Tested - guaranteed not to leak</p>			<p>\$ 32</p>
<p>1 1/2" straight-thru Ball Valve Type 2 Tested - guaranteed not to leak</p>			<p>\$ 29</p>
<p><i>ButterFly Valves, both Manual & Automatic</i></p>			
<p>BFV # 1 2" Engraved with 'VNE 304 # 14236 China' Practically new excellent seal</p>			<p>\$ 75</p>
<p>BFV # 2 2" Engraved '304L/3 2 CH 900147' Positioning collar under handle is missing</p>			<p>\$ 55</p>
<p>BFV # 3 2 1/2" No identifying engraving; New Seal; Positioning collar missing</p>			<p>\$ 89</p>

BFV # 4
2 1/2" No identifying engraving



\$ 79

BFV # 5
1 1/2"
Engraved 'Swiss Made 316 L'
This valve was used next to a receiver group - 'Open' for milking - 'Closed' for washing with a 5/16" hole drilled thru disc



\$ 65

BFV # 9
3".
This valve was used next to a receiver group 'Open' for milking, 'Closed' for washing with a notch filed thru disc. Engraved 'Taiwan'



\$ 65

ButterFly Valves - New

New! - BFV # 6
Engraved 2" 304 SC01D899




\$ 125

New! - BFV # 7
Engraved 3" 304



\$ 115

New! - BFV # 8
3" Engraved boep SUS 304 CP 3"



\$ 115

BF Valve # 11
2" Automatic
Reconditioned



\$ 225

BF Valve # 12 -
Reconditioned
3" Automatic



\$ 125

BF Valve # 13
New
3" Automatic



\$ 345

BF Valve # 14
New
2" Automatic



\$ 295